


**Vruty se zápusťnou čokovitou hlavou s křížovou drážkou**


<b>drážka</b>	Pozidrive
<b>materiál</b>	ocel kalená
<b>povrch</b>	ZB - zinek bílý ZZ - zinek žlutý

d	3	3,5	4	4,5	5	6
d	6,0	7,0	8,0	8,8	9,7	11,6
k max.	2,5	2,9	3,3	3,7	4	4,7
f	1,1	1,25	1,4	1,6	1,75	2
bit	PZ 1	PZ 2	PZ 2	PZ 2	PZ 2	PZ 3

Rozměr	d x l	Povrch	
		ZB	ZZ
<b>2,5</b>	2,5 x 12	•	
	2,5 x 16	•	
	2,5 x 20	•	
	2,5 x 25	•	
	2,5 x 30	•	
<b>3,0</b>	3,0 x 10	•	
	3,0 x 12	•	
	3,0 x 16	•	
	3,0 x 20	•	
	3,0 x 25	•	
	3,0 x 30	•	
	3,0 x 35	•	
	3,0 x 40	•	
	3,0 x 45	•	
	3,0 x 50	•	
<b>3,5</b>	3,5 x 10	•	
	3,5 x 12	•	
	3,5 x 16	•	
	3,5 x 20	•	
	3,5 x 25	•	
	3,5 x 30	•	
	3,5 x 35	•	
	3,5 x 40	•	
	3,5 x 45	•	
	3,5 x 50	•	

Rozměr	d x l	Povrch	
		ZB	ZZ
<b>4,0</b>	4,0 x 10	•	
	4,0 x 12	•	
	4,0 x 16	•	
	4,0 x 20	•	
	4,0 x 25	•	
	4,0 x 30	•	
	4,0 x 35	•	
	4,0 x 40	•	
	4,0 x 45	•	
	4,0 x 50	•	
4,0 x 70	•		
<b>4,5</b>	4,5 x 12	•	
	4,5 x 16	•	
	4,5 x 20	•	
	4,5 x 25	•	
	4,5 x 30	•	
	4,5 x 35	•	
	4,5 x 40	•	
	4,5 x 70	•	

Rozměr	d x l	Povrch	
		ZB	ZZ
<b>5,0</b>	5,0 x 16	•	
	5,0 x 20	•	
	5,0 x 25	•	
	5,0 x 30	•	
	5,0 x 35	•	
	5,0 x 40	•	
	5,0 x 45	•	
	5,0 x 50	•	
	5,0 x 60	•	
	5,0 x 70	•	
5,0 x 80	•		
5,0 x 90	•		
5,0 x 100	•		
<b>6,0</b>	6,0 x 20	•	
	6,0 x 25	•	
	6,0 x 30	•	
	6,0 x 35	•	
	6,0 x 40	•	
	6,0 x 45	•	
	6,0 x 50	•	
	6,0 x 60	•	
	6,0 x 70	•	
	6,0 x 80	•	
6,0 x 90	•		
6,0 x 100	•		